


## RIV 5100

Water meter fitting kit M/F  
(2 hose-unions + 2 swivel nuts + 2 gaskets)

### Tech drawings and tables




DN	Code	Ø	H	F	H1	KG	P/box
1/2" x 3/4"	025100000187	14,8	45,5	13	36,5	0,080	1
3/4" x 1"	025100000230	21	57	16	45,5	0,126	1
1" x 1"1/4"	025100000272	25,5	60,5	17,4	46,5	0,243	1
1"1/4 x 1"1/2"	025100000312	32,5	71	20	56	0,361	1
1"1/2 x 2"	025100000350	38,5	80,5	21	66	0,515	1
2"x2"1/2"	025100000393	50	94	28,5	76	1,83	1

## Technical data

<b>Connections</b>	Female ISO 7/1Rp (parallel), Male ISO 7/1R (tapered), screwed ring ISO 228/1
<b>Limit</b>	-20 °C (without liquid) + 110 °C
<b>Notes</b>	The max.working pressure (PN) means at a room temperature of about 23 °C.

## Pressure Loss Chart



## Temperature/Pressure

